

# MPC5607B\_1M03Y

## Mask Set Errata



# Mask Set Errata for Mask 1M03Y

## Revision History

This report applies to mask 1M03Y for these products:

- MPC5607B
- MPC5605B
- MPC5606B

**Table 1. Revision History**

Revision	Date	Significant Changes
16th	1/2023	The following errata were revised. <ul style="list-style-type: none"> <li>• ERR007394</li> </ul>
3rd February 2022	4/2022	The following errata were added. <ul style="list-style-type: none"> <li>• ERR009682</li> <li>• ERR003435</li> <li>• ERR050459</li> <li>• ERR008970</li> <li>• ERR011235</li> <li>• ERR009764</li> <li>• ERR009976</li> <li>• ERR009978</li> <li>• ERR010755</li> <li>• ERR050575</li> <li>• ERR011295</li> <li>• ERR011294</li> <li>• ERR011293</li> <li>• ERR008933</li> <li>• ERR008951</li> </ul> The following errata were revised. <ul style="list-style-type: none"> <li>• ERR007589</li> <li>• ERR007274</li> <li>• ERR007394</li> <li>• ERR004146</li> </ul>
16th July 2014	7/2014	The following errata were added. <ul style="list-style-type: none"> <li>• ERR007589</li> <li>• ERR008227</li> </ul>

*Table continues on the next page...*

**Table 1. Revision History (continued)**

Revision	Date	Significant Changes
		<ul style="list-style-type: none"> <li>• ERR003442</li> <li>• ERR007938</li> <li>• ERR007688</li> <li>• ERR007953</li> </ul> <p>The following errata were revised.</p> <ul style="list-style-type: none"> <li>• ERR003247</li> <li>• ERR005569</li> </ul>
12 Dec 2013	12/2013	<p>The following errata were added.</p> <ul style="list-style-type: none"> <li>• ERR006726</li> <li>• ERR006976</li> <li>• ERR006026</li> <li>• ERR007274</li> <li>• ERR007394</li> <li>• ERR004136</li> <li>• ERR006082</li> <li>• ERR006967</li> <li>• ERR005569</li> <li>• ERR007322</li> </ul> <p>The following errata were revised.</p> <ul style="list-style-type: none"> <li>• ERR004186</li> </ul>
15th Aug 2013	8/2013	No changes to errata with this revision
12 Aug 2013	8/2013	<p>The following errata were added.</p> <ul style="list-style-type: none"> <li>• ERR003606</li> </ul>
27th June 2013	6/2013	<p>The following errata were revised.</p> <ul style="list-style-type: none"> <li>• ERR004168</li> </ul>
24th June 2013	6/2013	No changes to errata with this revision
3	6/2013	<p>The following errata were removed.</p> <ul style="list-style-type: none"> <li>• ERR003606</li> </ul> <p>The following errata were added.</p> <ul style="list-style-type: none"> <li>• ERR006620</li> </ul> <p>The following errata were revised.</p> <ul style="list-style-type: none"> <li>• ERR003574</li> </ul>

*Table continues on the next page...*

**Table 1. Revision History (continued)**

Revision	Date	Significant Changes
		<ul style="list-style-type: none"> <li>• ERR002656</li> </ul>
30Aug2012	4/2013	The following errata were revised. <ul style="list-style-type: none"> <li>• ERR004168</li> <li>• ERR004146</li> <li>• ERR004340</li> </ul>
17MAY2012	8/2012	The following errata were removed. <ul style="list-style-type: none"> <li>• ERR003442</li> <li>• ERR003069</li> </ul> The following errata were added. <ul style="list-style-type: none"> <li>• ERR004168</li> <li>• ERR004405</li> <li>• ERR004146</li> <li>• ERR004186</li> <li>• ERR004340</li> </ul> The following errata were revised. <ul style="list-style-type: none"> <li>• ERR003570</li> <li>• ERR003606</li> <li>• ERR003512</li> </ul>
25AUG2011	4/2012	Initial Revision

## Errata and Information Summary

**Table 2. Errata and Information Summary**

Erratum ID	Erratum Title
<a href="#">ERR002656</a>	FlexCAN: Abort request blocks the CODE field
<a href="#">ERR002883</a>	FMPLL: FMPLL_CR[UNLOCK_ONCE] wrongly set
<a href="#">ERR002958</a>	MC_RGM: Clearing a flag at RGM_DES or RGM_FES register may be prevented by a reset
<a href="#">ERR002977</a>	MC_RGM: Long Reset Sequence Occurs on 'Short Functional' Reset Event
<a href="#">ERR003021</a>	LINFlex: Unexpected LIN timeout in slave mode
<a href="#">ERR003049</a>	MC_RGM: External Reset not asserted if Short Reset enabled
<a href="#">ERR003060</a>	MC_RGM: SAFE mode exit may be possible even though condition causing the SAFE mode request has not been cleared
<a href="#">ERR003080</a>	ADC: CTUEN bit in ADC.MCR register cannot be reset if a BCTU channel is enabled
<a href="#">ERR003119</a>	SWT: SWT interrupt does not cause STOP0 mode exit

*Table continues on the next page...*

Table 2. Errata and Information Summary (continued)

Erratum ID	Erratum Title
<a href="#">ERR003190</a>	MC_ME: Main VREG not disabled during STOP0 or HALT0 mode if RUN[0..3] mode selects FXOSC to be running and target mode selects FXOSC as system clock
<a href="#">ERR003195</a>	LINFlex: Limitations for DMA access to LINFlex
<a href="#">ERR003202</a>	MC_ME: Invalid Configuration not flagged if PLL is on while OSC is off.
<a href="#">ERR003209</a>	NMI pin configuration limitation in standby mode
<a href="#">ERR003210</a>	PA[1] pull-up enabled when NMI activated
<a href="#">ERR003219</a>	MC_CGM: System clock may stop for case when target clock source stops during clock switching transition
<a href="#">ERR003242</a>	PB[10],PD[0:1] pins configuration during standby
<a href="#">ERR003247</a>	MC_ME: A mode transition will not complete if the FlexCAN is disabled for target mode at MC_ME and is enabled at the FlexCAN peripheral
<a href="#">ERR003407</a>	FlexCAN: CAN Transmitter Stall in case of no Remote Frame in response to Tx packet with RTR=1
<a href="#">ERR003435</a>	In LQFP176 GPI and analog input are not supported on PB[8] and PB[9]
<a href="#">ERR003442</a>	CMU monitor: FXOSC/FIRC and FMPLL/FIRC relation
<a href="#">ERR003446</a>	CTU : The CTU (Cross Trigger Unit) CLR_FLAG in EVTCFGR register does not function as expected
<a href="#">ERR003449</a>	DEBUG: Device may hang due to external or 'functional' reset while using debug handshaking mechanism
<a href="#">ERR003466</a>	LINFlexD: Register bus aborts are not generated on illegal accesses to reserved addresses within the register address space of LINFlexD
<a href="#">ERR003512</a>	ECSM: ECSM_PFEDR displays incorrect endianness
<a href="#">ERR003556</a>	DMA_MUX : Low Power Entry may not be completed when peripherals run on divided clock with DMA enabled mode
<a href="#">ERR003570</a>	MC_ME: Possibility of Machine Check on Low-Power Mode Exit
<a href="#">ERR003574</a>	MC_RGM: A non-monotonic ramp on the VDD_HV/BV supply can cause the RGM module to clear all flags in the DES register
<a href="#">ERR003606</a>	32KHz SXOSC stops oscillating during STANDBY mode exit
<a href="#">ERR004136</a>	XOSC and IRCOSC: Bus access errors are generated in only half of non-implemented address space of XOSC and IRCOSC, and the other half of address space is mirrored
<a href="#">ERR004146</a>	SARADC: Interrupted conversions are aborted, but may not be properly restored
<a href="#">ERR004168</a>	ADC: Abort switch aborts the ongoing injected channel as well as the upcoming normal channel
<a href="#">ERR004186</a>	ADC: Do not trigger ABORT or ABORTCHAIN prior to the start of CTU triggered ADC conversions and do not trigger ABORTCHAIN prior to the start of INJECTED triggered ADC conversions.
<a href="#">ERR004340</a>	LINFlexD: Buffer overrun can not be detected in UART Rx FIFO mode
<a href="#">ERR004405</a>	SR bit of LINFlexD GCR register is not cleared automatically by hardware

*Table continues on the next page...*

Table 2. Errata and Information Summary (continued)

Erratum ID	Erratum Title
<a href="#">ERR005569</a>	ADC: The channel sequence order will be corrupted when a new normal conversion chain is started prior to completion of a pending normal conversion chain
<a href="#">ERR006026</a>	DSPI: Incorrect SPI Frame Generated in Combined Serial Interface Configuration
<a href="#">ERR006082</a>	LINFlexD : LINS bits in LIN Status Register(LINSR) are not usable in UART mode.
<a href="#">ERR006620</a>	FLASH: ECC error reporting is disabled for Address Pipelining Control (APC) field greater than Read Wait-State Control (RWSC) field.
<a href="#">ERR006726</a>	NPC: MCKO clock may be gated one clock period early when MCKO frequency is programmed as SYS_CLK/8.and gating is enabled
<a href="#">ERR006967</a>	eDMA: Possible misbehavior of a preempted channel when using continuous link mode
<a href="#">ERR006976</a>	MC_ME: SAFE mode not entered immediately on hardware-triggered SAFE mode request during STOP0 mode
<a href="#">ERR007274</a>	LINFlexD: Consecutive headers received by LIN Slave triggers the LIN FSM to an unexpected state
<a href="#">ERR007322</a>	FlexCAN: Bus Off Interrupt bit is erroneously asserted when soft reset is performed while FlexCAN is in Bus Off state
<a href="#">ERR007394</a>	MC_ME: Incorrect mode may be entered on low-power mode exit.
<a href="#">ERR007589</a>	LINFlexD: Spurious timeout error when switching from UART to LIN mode or when resetting LINTCSR[MODE] bit in LIN mode
<a href="#">ERR007688</a>	RTC: An API interrupt may be triggered prematurely after programming the API timeout value
<a href="#">ERR007938</a>	ADC: Possibility of missing CTU conversions
<a href="#">ERR007953</a>	ME: All peripherals that will be disabled in the target mode must have their interrupt flags cleared prior to target mode entry
<a href="#">ERR008227</a>	CGM & ME: The peripheral set clock must be active during a peripheral clock enable or disable request
<a href="#">ERR008933</a>	LINFlexD: Inconsistent sync field may cause an incorrect baud rate and the Sync Field Error Flag may not be set
<a href="#">ERR008951</a>	I2C: Attempting a start cycle while the bus is busy may generate a short clock pulse
<a href="#">ERR008970</a>	LINFlexD: Spurious bit error in extended frame mode may cause an incorrect Idle State
<a href="#">ERR009682</a>	SPI: Inconsistent loading of shift register data into the receive FIFO following an overflow event
<a href="#">ERR009764</a>	SARADC : DMA interface limitation depending on PBRIDGE/SARADC clock ratio
<a href="#">ERR009976</a>	DSPI: Incorrect data received by master with Modified transfer format enabled when using Continuous serial communication clock mode
<a href="#">ERR009978</a>	eMIOS: Unexpected channel flag assertion during GPIO to MCB mode transition
<a href="#">ERR010755</a>	DSPI: Transmit and Receive FIFO fill flags in status register is not cleared when DMA is improperly configured
<a href="#">ERR011235</a>	EMIOS: Any Unified Channel running in OPWMB or OPWMCB mode may function improperly if the source counter bus is generated by Unified channel in MC mode

*Table continues on the next page...*

Table 2. Errata and Information Summary (continued)

Erratum ID	Erratum Title
<a href="#">ERR011293</a>	EMIOS: For any UC operating in OPWFMB mode the Channel Count register should not be written with a value greater than Channel B Data register value
<a href="#">ERR011294</a>	EMIOS: OPWFMB and MCB mode counter rollover resets the counter to 0x0 instead of 0x1 as mentioned in the specification
<a href="#">ERR011295</a>	EMIOS: In OPWFMB mode, A1/B1 registers do not get reloaded with A2/B2 register values if counter value returns 0x1 after counter wrap condition
<a href="#">ERR050459</a>	SXOSC: Clock output may contain extra clock pulses in Normal mode
<a href="#">ERR050575</a>	eMIOS: Any Unified Channel running in OPWMCB mode may function improperly if the lead or trail dead time insertion features is used and its timebase is generated by Unified channel in MCB mode

# Known Errata

## ERR002656: FlexCAN: Abort request blocks the CODE field

### Description

An Abort request to a transmit Message Buffer (TxMB) can block any write operation into its CODE field. Therefore, the TxMB cannot be aborted or deactivated until it completes a valid transmission (by winning the CAN bus arbitration and transmitting the contents of the TxMB).

### Workaround

Instead of aborting the transmission, use deactivation instead.

Note that there is a chance that the deactivated TxMB can be transmitted without setting IFLAG and updating the CODE field if it is deactivated.

## ERR002883: FMPLL: FMPLL\_CR[UNLOCK\_ONCE] wrongly set

### Description

If the FMPLL is locked and a functional reset occurs, FMPLL\_CR[UNLOCK\_ONCE] is automatically set even when the FMPLL has not lost lock.

### Workaround

Do not use the FMPLL\_CR[UNLOCK\_ONCE] when a functional reset occurs.

## ERR002958: MC\_RGM: Clearing a flag at RGM\_DES or RGM\_FES register may be prevented by a reset

### Description

Clearing a flag at RGM\_DES and RGM\_FES registers requires two clock cycles because of a synchronization mechanism. As a consequence if a reset occurs while clearing is on-going the reset may interrupt the clearing mechanism leaving the flag set.

Note that this failed clearing has no impact on further flag clearing requests.

### Workaround

No workaround for all reset sources except SW reset.

Note that in case the application requests a SW reset immediately after clearing a flag in RGM\_xES the same issue may occur. To avoid this effect the application must ensure that flag clearing has completed by reading the RGM\_xES register before the SW reset is requested.

## ERR002977: MC\_RGM: Long Reset Sequence Occurs on 'Short Functional' Reset Event

### Description

If a 'functional' reset source is configured to initiate a short reset sequence via setting of the appropriate RGM\_FESS bit and also configured to assert the external reset pad via setting of the appropriate RGM\_FBRE bit, its assertion will not initiate a short reset starting with PHASE3 but rather a long reset sequence starting with PHASE1.



## Workaround

Do not configure 'functional' resets that are configured to initiate a short reset sequence to also assert the external reset pad. In other words, if RGM\_FESS[i] is '1', RGM\_FBRE[i] should be '0'.

## ERR003021: LINFlex: Unexpected LIN timeout in slave mode

### Description

If the LINFlex is configured in LIN slave mode, an unexpected LIN timeout event (LINESR[OCF]) may occur during LIN Break reception.

### Workaround

It is recommended to disable this functionality during LINFlex initialization by clearing LINTCSR[IOT] and LINIER[OCIE] bits, and ignore timeout events.

## ERR003049: MC\_RGM: External Reset not asserted if Short Reset enabled

### Description

For the case when the External Reset is enabled for a specific reset source at RGM\_FBRE and a short reset is requested for the same reset source at RGM\_FESS the External Reset is not asserted.

### Workaround

None

## ERR003060: MC\_RGM: SAFE mode exit may be possible even though condition causing the SAFE mode request has not been cleared

### Description

A SAFE mode exit should not be possible as long as any condition that caused a SAFE mode entry is still active. However, if the corresponding status flag in the RGM\_FES register has been cleared, the SAFE mode exit may incorrectly occur even though the actual condition is still active.

### Workaround

Software must clear the SAFE mode request condition at the source before clearing the corresponding RGM\_FES flag. This will ensure that the condition is no longer active when the RGM\_FES flag is cleared and thus the SAFE mode exit can occur under the correct conditions.

## ERR003080: ADC: CTUEN bit in ADC.MCR register cannot be reset if a BCTU channel is enabled

### Description

While any BCTU channels is enabled (CTU.EVTCFGRx.TM =1), the CTU will continuously send trigger requests to ADC. If CTUEN bit in MCR is reset while BCTU channels are enabled, the ADC DTU trigger state may become undefined and ADC module may not service trigger request from CTU anymore.

### Workaround

Ensure ADC.MCR.CTUEN is set before enabling any CTU channels (CTU.EVTCFGRx.TM =1). Ensure all CTU channels are disabled (CTU.EVTCFGRx.TM =0) before ADC.MCR.CTUEN is cleared.

## ERR003119: SWT: SWT interrupt does not cause STOP0 mode exit

### Description

While in STOP0 mode, if the SWT is configured to generate an interrupt and the system clock is disabled (ME\_STOP0\_MC[SYSCLK] = 0xF), a SWT interrupt event will not trigger an exit from STOP0 mode.

Other internal or external wakeup events (RTC, API, WKUP pins) are not affected and will trigger a STOP0 exit independent of the ME\_STOP0\_MC[SYSCLK] configuration.

### Workaround

If a SWT interrupt is to be used to wake the device during STOP0 mode, software may not disable the system clock (ME\_STOP0\_MC[SYSCLK] != 0xF).

## ERR003190: MC\_ME: Main VREG not disabled during STOP0 or HALT0 mode if RUN[0..3] mode selects FXOSC to be running and target mode selects FXOSC as system clock

### Description

If STOP0 or HALT0 is configured with ME\_[mode]\_MC.MVRON = '0', ME\_[mode]\_MC.FIRCON = '0' and ME\_[mode]\_MC.SYSCLK = '0010/0011' the Main VREG will nevertheless remain enabled during the STOP0 mode if the previous RUN[0..3] mode is configured with ME\_RUN[0..3]\_MC.FXOSCON = '1'. This will result in increased current consumption of 500uA than expected.

### Workaround

Before entering STOP0 or HALT0 mode with the following configuration - ME\_[mode]\_MC.MVRON = '0', ME\_[mode]\_MC.FIRCON = '0' and ME\_[mode]\_MC.SYSCLK = '0010/0011' - ensure the RUN[0..3] mode switches off FXOSC - ME\_RUN[0..3]\_MC.FXOSCON = '0' before attempting to low power mode transition.

## ERR003195: LINFlex: Limitations for DMA access to LINFlex

### Description

The DMA handshaking to the LINFlex can fail when the LINFlex operates on a divided peripheral clock.

### Workaround

Don't divide the LINFlex peripheral clock if DMA access is required.

## ERR003202: MC\_ME: Invalid Configuration not flagged if PLL is on while OSC is off.

### Description

PLL clock generation requires oscillator to be on. Mode configuration in which PLLON bit is "1" and OSCON bit is "0" is an invalid mode configuration. When ME\_XXX\_MC registers are attempted with such an invalid configuration, ME\_IS.I\_CONF is not getting set which is wrong. Eventually the mode transition did not complete and system hangs.

### Workaround

Always program Oscillator to be on when PLL is required.

## ERR003209: NMI pin configuration limitation in standby mode

### Description

NMI pin cannot be configured to generate Non Maskable Interrupt event to the core (WKPU\_NCR[NDSS] = "00") if the following standby mode is to be used:

- NMI pin enabled for wake-up event,
- standby exit sequence boot from RAM,
- code flash module power-down on standby exit sequence.

With following configuration following scenario may happen:

1. System is in standby
2. NMI event is triggered on PA[1]
3. System wakeup z0 core power domain.
4. z0 core reset is released and NMI event is sampled by core on first clock-edge.
5. z0 core attempt to fetch code at 0x10 address (IVPR is not yet initialized by application) and receive an exception since flash is not available
6. z0 core enter machine check and execution is stalled.

### Workaround

If NMI is configured as wake-up source, WKPU\_NCR[NDSS] must be configured as "11". This will ensure no NMI event is triggered on the core but ensure system wakeup is triggered.

After standby exit, core will boot and configure its IVOR/IVPR, it may then re-configure WKPU\_NCR:DSS to the appropriate configuration for enabling NMI/CI/MCP.

## ERR003210: PA[1] pull-up enabled when NMI activated

### Description

When NMI is enabled (either WKPU\_NCR[NREE] or WKPU\_NCR[NFEE] set to '1'), PA[1] pull-up is automatically activated independently from SIUL\_PCR1[WPS] and SIUL\_PCR1[WPE].

This has no effect during STANDBY mode. PA[1] pull-up is then correctly configured through WKPU\_WIPUER[IPUE[2]].

### Workaround

None

## ERR003219: MC\_CGM: System clock may stop for case when target clock source stops during clock switching transition

### Description

The clock switching is a two step process. The availability of the target clock is first verified. Then the system clock is switched to the new target clock source within two target clock cycles.

For the case when the FXOSC stops during the required two cycles, the switching process may not complete, causing the system clock to stop and prevent further clock switching. This may happen if one of the following cases occurs while the system clock source is switching to FXOSC:

- FXOSC oscillator failure

- SAFE mode request occurs, as this mode will immediately switch OFF the FXOSC (refer to ME\_SAFE\_MC register configuration)

#### Workaround

The device is able to recover through any reset event ('functional', 'destructive', internal or external), so typically either the SWT (internal watchdog) will generate a reset or, in case it is used in the application, the external watchdog will generate an external reset. In all cases the devices will restart properly after reset.

To reduce the probability that this issue occurs in the application, disable SAFE mode transitions when the device is executing a mode transition with the FXOSC as the system clock source in the target mode.

### ERR003242: PB[10],PD[0:1] pins configuration during standby

#### Description

PB[10], PD[0:1] are the pins having both wake-up functionality and analog functionality.

As for all wake-up pins, it must be driven either high level or low level (possibly using the internal pull-up) during standby.

In case the pin is connected to external component providing analog signal, it is important to check that this external analog signal is either lower than  $0.2 \cdot VDD_{HV}$  or higher than  $0.8 \cdot VDD_{HV}$  not to incur extra consumption.

#### Workaround

None

### ERR003247: MC\_ME: A mode transition will not complete if the FlexCAN is disabled for target mode at MC\_ME and is enabled at the FlexCAN peripheral

#### Description

If a FlexCAN module is enabled for the current mode at MC\_ME using the ME\_RUN\_PCx/ME\_PCTLx registers and also enabled at the FlexCAN Module Configuration Register, for the case when the target mode (run or low power) disables the FlexCAN module, this transition will only complete if the FlexCAN is disabled at the FlexCAN peripheral prior to the target mode transition.

#### Workaround

Before initiating the target mode change at the MC\_ME the FlexCAN Module Configuration Register should be configured to set Freeze Enable, Halt and Module Disable (FLEXCAN\_MCR) i.e.  $FLEXCAN\_MCR[FRZ] = FLEXCAN\_MCR[HALT] = FLEXCAN\_MCR[MDIS] = 1$ .

### ERR003407: FlexCAN: CAN Transmitter Stall in case of no Remote Frame in response to Tx packet with RTR=1

#### Description

FlexCAN does not transmit an expected message when the same node detects an incoming Remote Request message asking for any remote answer.

The issue happens when two specific conditions occur:

- 1) The Message Buffer (MB) configured for remote answer (with code "a") is the last MB. The last MB is specified by Maximum MB field in the Module Configuration Register (MCR[MAXMB]).
- 2) The incoming Remote Request message does not match its ID against the last MB ID.

While an incoming Remote Request message is being received, the FlexCAN also scans the transmit (Tx) MBs to select the one with the higher priority for the next bus arbitration. It is expected that by the Intermission field it ends up with a selected candidate (winner). The coincidence of conditions (1) and (2) above creates an internal corner case that cancels the Tx winner and therefore

no message will be selected for transmission in the next frame. This gives the appearance that the FlexCAN transmitter is stalled or "stops transmitting".

The problem can be detectable only if the message traffic ceases and the CAN bus enters into Idle state after the described sequence of events.

There is NO ISSUE if any of the conditions below holds:

- a) The incoming message matches the remote answer MB with code "a".
- b) The MB configured as remote answer with code "a" is not the last one.
- c) Any MB (despite of being Tx or Rx) is reconfigured (by writing its CS field) just after the Intermission field.
- d) A new incoming message sent by any external node starts just after the Intermission field.

#### Workaround

Do not configure the last MB as a Remote Answer (with code "a").

### ERR003435: In LQFP176 GPI and analog input are not supported on PB[8] and PB[9]

#### Description

In LQFP176 package pin 60 (PB[9]) and pin 61 (PB[8]) do not support the GPI and analog input features.

The 32KHz SXOSC functionality remains available.

#### Workaround

None

### ERR003442: CMU monitor: FXOSC/FIRC and FMPLL/FIRC relation

#### Description

Functional CMU monitoring can only be guaranteed when the following conditions are met:

- FXOSC frequency must be greater than  $(FIRC / 2^{RCDIV}) + 0.5\text{MHz}$  in order to guarantee correct FXOSC monitoring
- FMPLL frequency must be greater than  $(FIRC / 4) + 0.5\text{MHz}$  in order to guarantee correct FMPLL monitoring

#### Workaround

Refer to description

### ERR003446: CTU : The CTU (Cross Trigger Unit) CLR\_FLAG in EVTCFGR register does not function as expected

#### Description

If the CTU CLR\_FLG is set and the CTU is idle, a PIT triggered request to the CTU does not result in the correct ADC channel number being latched. The previous ADC channel number is latched instead of the requested channel number.

#### Workaround

There is no software workaround to allow the CLR\_FLAG functionality to operate correctly. Do not program the CLR\_FLAG bit to '1'.

## ERR003449: DEBUG: Device may hang due to external or 'functional' reset while using debug handshaking mechanism

### Description

If the low-power mode debug handshake has been enabled and an external reset or a 'functional' reset occurs while the device is in a low-power mode, the device will not exit reset.

### Workaround

The NPC\_PCR[LP\_DBG\_EN] bit must be cleared to ensure the correct reset sequence.

## ERR003466: LINFlexD: Register bus aborts are not generated on illegal accesses to reserved addresses within the register address space of LINFlexD

### Description

Register bus aborts are not generated on illegal accesses to reserved addresses within the register address space of LINFlexD. This is applicable to LINFlex modules supporting master-only mode.

### Workaround

None

## ERR003512: ECSM: ECSM\_PFEDR displays incorrect endianness

### Description

The ECSM\_PFEDR register reports ECC data using incorrect endianness. For example, a flash location that contains the data 0xAABBCCDD would be reported as 0xDDCCBBAA at ECSM\_PFEDR.

This 32-bit register contains the data associated with the faulting access of the last, properly-enabled flash ECC event. The register contains the data value taken directly from the data bus.

### Workaround

Software must correct endianness.

## ERR003556: DMA\_MUX : Low Power Entry may not be completed when peripherals run on divided clock with DMA enabled mode

### Description

System may not enter into Low Power Mode (HALT/STOP/STANDBY) when all the below conditions are true simultaneously:

1. A Peripheral with DMA capability is programmed to work on divided clock.
2. Above peripheral is programmed to be stopped in Low Power Mode and active in RUN Mode.
3. Above Peripheral is active with DMA transfer while Software requests change to Low Power mode.

### Workaround

Software should ensure that all the DMA enabled peripherals have completed their transfer before requesting Low Power mode Entry

## ERR003570: MC\_ME: Possibility of Machine Check on Low-Power Mode Exit

### Description

When executing from the flash and entering a Low-Power Mode (LPM) where the flash is in low-power or power-down mode, 2-4 clock cycles exist at the beginning of the RUNx to LPM transition during which a wakeup or interrupt will generate a checkstop due to the flash not being available on RUNx mode re-entry. This will cause either a checkstop reset or machine check interrupt.

### Workaround

If the application must avoid the reset, two workarounds are suggested:

- 1) Configure the application to handle the machine check interrupt in RAM dealing with the problem only if it occurs
- 2) Configure the MCU to avoid the machine check interrupt, executing the transition into low power modes in RAM

There is no absolute requirement to work around the possibility of a checkstop reset if the application can accept the reset, and associated delays, and continue. In this event, the WKPU.WISR will not indicate the channel that triggered the wakeup though the F\_CHKSTOP flag will indicate that the reset has occurred. The F\_CHKSTOP flag could still be caused by other error conditions so the startup strategy from this condition should be considered alongside any pre-existing strategy for recovering from an F\_CHKSTOP condition.

## ERR003574: MC\_RGM: A non-monotonic ramp on the VDD\_HV/BV supply can cause the RGM module to clear all flags in the DES register

### Description

During power up, if there is non-monotonicity in power supply ramp with a voltage drop > 100 mV due to external factors, such as battery cranking or weak board regulators, the SoC may show a no flag condition (F\_POR == LVD12 == LVD27 == 0).

Under these situations, it is recommended that customers use a workaround to detect a POR.

In all cases, initialization of the device will complete normally.

### Workaround

The software workaround need only be applied when neither the F\_POR, LVD27 nor LVD12 flag is set and involves checking SRAM contents and monitoring for ECC errors during this process. In all cases, an ECC error is assumed to signify a power-on reset (POR).

Three suggestions are made for software workarounds. In each case, if POR is detected all RAM should be initialized otherwise no power-on condition is detected and it is possible to initialize only needed parts of RAM while preserving required information.

Software workaround #1 :

An area of RAM can be reserved by the compiler into which a KEY, such as 0x3EC1\_9678, is written. This area can be checked at boot and if the KEY is incorrect or an ECC error occurs, POR can be assumed and the KEY should be set. Use of a KEY increases detection rate to 31 bits ( $\approx 10^{-9}$ ) or 23 bits ( $\approx 5 \cdot 10^{-6}$ ) instead of 7 bit linked to ECC ( $\approx 10^{-2}$ )

Software workaround #2 :

When runtime data should be retained and RAM only fully re-initialized in the case of POR, a checksum should be calculated on the runtime data area after each data write. In the event of a reset where no flags are set, the checksum should be read and compared with one calculated across the data area. If reading the checksum and the runtime data area succeeds without an ECC error, and the checksums match, it is assumed than no POR occurred. The checksum could be a CRC, a CMAC or any other suitable hash.

Software workaround #3 :

Perform a read of memory space that is expected to be retained across an LVD reset. If there are no ECC errors, it can be assumed that an LVD reset occurred rather than a POR.

## ERR003606: 32KHz SXOSC stops oscillating during STANDBY mode exit

### Description

During STANDBY mode exit the internal weak pull-up of PB[8] (XTAL) and PB[9] (EXTAL) pins are activated for 12µs (run from RAM) to 25µs (run from flash). While the pull-ups are activated the 32kHz SXOSC stops oscillating properly causing a loss of counts (1 to 3) on RTC/API counter.

The number of missing counts may vary with 32kHz XTAL, MCU and board process, temperature and voltage. This means that there is no SW work around to compensate by SW the missing oscillations/counts.

The impact of the missing clocks on the precision of the 32kHz SXOSC and RTC/API in the application depends on the frequency of the periodic wake-up from STANDBY versus the required RTC precision. This must be evaluated specifically for each application.

### Workaround

If the full precision of the 32kHz SXOSC is required by the application then a product with a dedicated bonding option, where the GPI PB[8] and PB[9] have been removed, must be used.

The commercial products with this 32kHz dedicated bonding are as follows:

- For the 1.5M Flash device, SC667183xxxxxx,
- For the 1M Flash device, SC667215xxxxxx,
- For the 768k Flash device, SC667214xxxxxx.

These 32Khz dedicated bonding products will have a different MIDR2 respect to the normal bonding ones as following:

- normal 32Khz bonding products -> MIDR2=0x32004210
- dedicated 32Khz bonding products -> MIDR2=0x32004290

Note that as a result of this bonding change, the products indicated above do not support GPI PB[8] and PB[9] functionality.

## ERR004136: XOSC and IRCOSC: Bus access errors are generated in only half of non-implemented address space of XOSC and IRCOSC, and the other half of address space is mirrored

### Description

Bus access errors are generated in only half of the non-implemented address space of Oscillator External Interface (40MHz XOSC) and IRCOSC Digital Interface (16MHz Internal RC oscillator [IRC]). In both cases, the other half of the address space is a mirrored version of the 1st half. Thus reads/writes to the 2nd half of address space will actually read/write the registers of corresponding offset in the 1st half of address space.

### Workaround

Do not access unimplemented address space for XOSC and IRCOSC register areas OR write software that is not dependent on receiving an error when access to unimplemented XOSC and IRCOSC space occurs.

## ERR004146: SARADC: Interrupted conversions are aborted, but may not be properly restored

### Description

When a triggered conversion interrupts an in process conversion in the Successive Approximation Analog to Digital Converter (SARADC), it is possible that the aborted conversion does not get restored to the SARADC and is not converted during the chain. Vulnerable configurations are:

- Injected chain over a normal chain



- Cross Triggering Unit (CTU) trigger over a normal chain
- CTU trigger over an injected chain

When any of these triggers arrive while the SARADC is in the conversion stage of the sample and conversion, the sample is discarded and is not restored. This means that the channel data register (SARADC\_xCDRn) will not show the channel as being valid and the register SARADC\_xCIPRn field CEOCFRx will not indicate a pending conversion. The sample that was aborted is lost.

If the injection occurs when the finite state machine switches from the sample phase, it is possible that on resuming normal chain, the chain is restored from an incorrect channel. This may lead to a second conversion on one of the channels in the chain.

When the trigger arrives during the final (last) channel conversion in a normal or injected chain, the same failure mode can cause two ECH (End of chain) interrupts to be raised in the interrupt register (SARADC\_ISR).

If the trigger arrives during the sampling phase of the last channel in the chain, an ECH is triggered immediately, the trigger is processed and the channel is restored and after sampling/conversion, a second ECH interrupt occurs.

In scan mode, the second ECH does not occur if the trigger arrives during the conversion phase. In one-shot mode, a trigger arriving during the conversion phase of the last channel restarts the whole conversion chain and the next ECH occurs at completion of that chain.

### Workaround

The application should check for valid data using the Channel Data Register, Internal Channel Data Register or Test Channel Data Register (CDR) status bits or the CEOCFRx registers to ensure all expected channels have converted. This can be tested by running a bitwise AND and an XOR with either the Channel Conversion Mask Register (JCMRx) or the Channel Conversion Mask Register (NCMRx) and the CEOCFRx registers during the JECH handler. Any non-zero value for  $(xCMRx \& (xCMRx \oplus CEOCFRx)) / (SARADC\_ICxCMRn \& (SARADC\_ICxCMRn \oplus SARADC\_IPICRn.EOC\_CHx))$  indicates that a channel has been missed and conversion should be requested again.

Spurious ECH interrupts can be detected by checking the NSTART/JSTART flags in the SARADC\_MSR Module Status Registers – if the flag remains set during an ECH interrupt then another interrupt will follow after the restored channel or chain has been sampled and converted.

The spurious ECH workaround above applies to single-shot conversions. In single-shot mode, NSTART changes from 1 to 0. Therefore, the user can rely on checking the NSTART bit to confirm if a spurious ECH has occurred. However, for scan mode, the NSTART bit will remain set during normal operation, so it cannot be relied upon to check for the spurious ECH issue. Consequently, if the CTU is being used in trigger mode, the conversions must be single-shot and not scan mode.

## ERR004168: ADC: Abort switch aborts the ongoing injected channel as well as the upcoming normal channel

### Description

If an Injected chain (jch1,jch2,jch3) is injected over a Normal chain (nch1,nch2,nch3,nch4) the Abort switch does not behave as expected.

Expected behavior:

Correct Case (without SW Abort on jch3): Nch1- Nch2(aborted) -Jch1 - Jch2 - Jch3 - Nch2(restored) - Nch3 - Nch4

Correct Case(with SW Abort on jch3): Nch1 - Nch2(aborted) -Jch1 - Jch2 - Jch3(aborted) - Nch2(restored) - Nch3 - Nch4

Observed unexpected behavior:

Fault1 (without SW abort on jch3): Nch1 - Nch2(aborted) - Jch1 - Jch2 - Jch3 - Nch3 - Nch4 (Nch2 not restored)

Fault2 (with SW abort on jch3): Nch1- Nch2 (aborted) - Jch1 - Jch2 - Jch3(aborted) - Nch4 (Nch2 not restored & Nch3 conversion skipped)

### Workaround

It is possible to detect the unexpected behavior by using the CEOCFR<sub>x</sub> register. The CEOCFR<sub>x</sub> fields will not be set for a not restored or skipped channel, which indicates this issue has occurred. The CEOCFR<sub>x</sub> fields need to be checked before the next Normal chain execution (in scan mode). The CEOCFR<sub>x</sub> fields should be read by every ECH interrupt at the end of every chain execution.

## **ERR004186: ADC: Do not trigger ABORT or ABORTCHAIN prior to the start of CTU triggered ADC conversions and do not trigger ABORTCHAIN prior to the start of INJECTED triggered ADC conversions.**

### Description

When ADC\_MCR[ABORT] or ADC\_MCR[ABORTCHAIN] is set prior to the ADC receiving a CTU trigger, the next CTU triggered ADC conversion will not be performed and further CTU triggered ADC conversions will be blocked.

When ADC\_MCR[ABORTCHAIN] is set prior to the ADC receiving an INJECTED trigger, the next INJECTED ADC conversion will not be performed. Following the ABORTCHAIN command the MCU behaviour does not meet the specification as ADC\_ISR[JECH] is not set and ADC\_MCR[ABORTCHAIN] is not cleared.

### Workaround

Do not program ADC\_MCR[ABORT] or ADC\_MCR[ABORTCHAIN] before the start of ADC conversions.

The case when CTU triggered ADC conversions are blocked should be avoided however it is possible to reactivate CTU conversions by clearing and setting ADC\_MCR[CTUEN].

## **ERR004340: LINFlexD: Buffer overrun can not be detected in UART Rx FIFO mode**

### Description

When the LINFlexD is configured in UART Receive (Rx) FIFO mode, the Buffer Overrun Flag (BOF) bit of the UART Mode Status Register (UARTSR) register is cleared in the subsequent clock cycle after being asserted.

User software can not poll the BOF to detect an overflow.

The LINFlexD Error Combined Interrupt can still be triggered by the buffer overrun. This interrupt is enabled by setting the Buffer Overrun Error Interrupt Enable (BOIE) bit in the LIN Interrupt enable register (LINIER). However, the BOF bit will be cleared when the interrupt routine is entered, preventing the user from identifying the source of error.

### Workaround

Buffer overrun errors in UART FIFO mode can be detected by enabling only the Buffer Overrun Interrupt Enable (BOIE) in the LIN interrupt enable register (LINIER).

## **ERR004405: SR bit of LINFlexD GCR register is not cleared automatically by hardware**

### Description

After setting the SR bit of GCR (Global Control Register) to reset the LinFlexD controller, this bit is not cleared automatically by the hardware, keeping the peripheral in reset state

### Workaround

This bit should be cleared by software to perform further operations

## ERR005569: ADC: The channel sequence order will be corrupted when a new normal conversion chain is started prior to completion of a pending normal conversion chain

### Description

If One shot mode is configured in the Main Configuration Register (MCR[MODE] = 0) the chained channels are automatically enabled in the Normal Conversion Mask Register 0 (NCMR0). If the programmer initiates a new chain normal conversion, by setting MCR[NSTART] = 0x1, before the previous chain conversion finishes, the new chained normal conversion will not follow the requested sequence of converted channels.

For example, if a chained normal conversion sequence includes three channels in following sequence: channel0, channel1 and channel2, the conversion sequence is started by MCR[NSTART] = 0x1. The software re-starts the next conversion sequence when MCR[NSTART] is set to 0x1 just before the current conversion sequence finishes.

The conversion sequence should be: channel0, channel1, channel2, channel0, channel1, channel2.

However, the conversion sequence observed will be: channel0, channel1, channel2, channel1, channel1, channel2. Channel0 is replaced by channel1 in the second chain conversion and channel1 is converted twice.

### Workaround

Ensure a new conversion sequence is not started when a current conversion is ongoing. This can be ensured by issuing the new conversion setting MCR[NSTART] only when MSR[NSTART] = 0.

Note: MSR[NSTART] indicates the present status of conversion. MSR[NSTART] = 1 means that a conversion is ongoing and MSR[NSTART] = 0 means that the previous conversion is finished.

## ERR006026: DSPI: Incorrect SPI Frame Generated in Combined Serial Interface Configuration

### Description

In the Combined Serial Interface (CSI) configuration of the Deserial Serial Peripheral Interface (DSPI) where data frames are periodically being sent (Deserial Serial Interface, DSI), a Serial Peripheral Interface (SPI) frame may be transmitted with incorrect framing.

The incorrect frame may occur in this configuration if the user application writes SPI data to the DSPI Push TX FIFO Register (DSPI\_PUSHR) during the last two peripheral clock cycles of the Delay-after-Transfer (DT) phase. In this case, the SPI frame is corrupted.

### Workaround

Workaround 1: Perform SPI FIFO writes after halting the DSPI.

To prevent writing to the FIFO during the last two clock cycles of DT, perform the following steps every time a SPI frame is required to be transmitted:

Step 1: Halt the DSPI by setting the HALT control bit in the Module Configuration Register (DSPI\_MCR[HALT]).

Step 2: Poll the Status Register's Transmit and Receive Status bit (DSPI\_SR[TRXS]) to ensure the DSPI has entered the HALT state and completed any in-progress transmission. Alternatively, if continuous polling is undesirable in the application, wait for a fixed time interval such as 35 baud clocks to ensure completion of any in-progress transmission and then check once for DSPI\_SR[TRXS].

Step 3: Perform the write to DSPI\_PUSHR for the SPI frame.

Step 4: Clear bit DSPI\_MCR[HALT] to bring the DSPI out of the HALT state and return to normal operation.

Workaround 2: Do not use the CSI configuration. Use the DSPI in either DSI-only mode or SPI-only mode.

Workaround 3: Use the DSPI's Transfer Complete Flag (TCF) interrupt to reduce worst-case wait time of Workaround 1.

Step 1: When a SPI frame is required to be sent, halt the DSPI as in Step 1 of Workaround 1 above.

Step 2: Enable the TCF interrupt by setting the DSPI DMA/Interrupt Request Select and Enable Register's Transmission Complete Request Enable bit (DSPI\_RSER[TCF\_RE])

Step 3: In the TCF interrupt service routine, clear the interrupt status (DSPI\_SR[TCF]) and the interrupt request enable (DSPI\_RSER[TCF\_RE]). Confirm that DSPI is halted by checking DSPI\_SR[TXRXS] and then write data to DSPI\_PUSHR for the SPI frame. Finally, clear bit DSPI\_MCR[HALT] to bring the DSPI out of the HALT state and return to normal operation.

## **ERR006082: LINFlexD : LINS bits in LIN Status Register(LINSR) are not usable in UART mode.**

### **Description**

When the LINFlexD module is used in the Universal Asynchronous Receiver/Transmitter (UART) mode, the LIN state bits (LINS3:0) in LIN Status Register (LINSR) always indicate the value zero. Therefore, these bits cannot be used to monitor the UART state.

### **Workaround**

LINS bits should be used only in LIN mode.

## **ERR006620: FLASH: ECC error reporting is disabled for Address Pipelining Control (APC) field greater than Read Wait-State Control (RWSC) field.**

### **Description**

The reference manual states the following at the Platform flash memory controller Access pipelining functional description.

"The platform flash memory controller does not support access pipelining since this capability is not supported by the flash memory array. As a result, the APC (Address Pipelining Control) field should typically be the same value as the RWSC (Read Wait-State Control) field for best performance, that is, BKn\_APC = BKn\_RWSC. It cannot be less than the RWSC."

The reference manual advises that the user must not configure APC to be less than RWSC and typically APC should equal RWSC. However the documentation does not prohibit the configuration of APC greater than RWSC and for this configuration ECC error reporting will be disabled. Flash ECC error reporting will only be enabled for APC = RWSC.

For the case when flash ECC is disabled and data is read from a corrupt location the data will be transferred via the system bus however a bus error will not be asserted and neither a core exception nor an ECSM interrupt will be triggered. For the case of a single-bit ECC error the data will be corrected but for a double-bit error the data will be corrupt.

### **Notes**

1. Both CFlash & DFlash are affected by this issue.
2. For single-bit and double-bit Flash errors neither a core exception nor an ECSM interrupt will be triggered unless APC=RWSC.
3. The Flash Array Integrity Check feature is not affected by this issue and will successfully detect an ECC error for all configurations of APC >= RWSC.
4. For the APC > RWSC configuration other than flash ECC error reporting there will be no other unpredictable behaviour from the flash.
5. The write wait-state control setting at PFCRx[BKn\_WWSC] has no affect on the flash. It is recommend to set WWSC = RWSC = APC.

### **Workaround**

PFCRx[BKy\_APC] must equal PFCRx PFCRx[BKy\_RWSC]. See datasheet for correct setting of RWSC.

## ERR006726: NPC: MCKO clock may be gated one clock period early when MCKO frequency is programmed as SYS\_CLK/8 and gating is enabled

### Description

The Nexus auxiliary message clock (MCKO) may be gated one clock period early when the MCKO frequency is programmed as SYS\_CLK/8 in the Nexus Port Controller Port Configuration Register (NPC\_PCR[MCKO\_DIV]=111) and the MCKO gating function is enabled (NPC\_PCR[MCKO\_GT]=1). In this case, the last MCKO received by the tool prior to the gating will correspond to the END\_MESSAGE state. The tool will not receive an MCKO to indicate the transition to the IDLE state, even though the NPC will transition to the IDLE state internally. Upon re-enabling of MCKO, the first MCKO edge will drive the Message Start/End Output (MSEO=11) and move the tool's state to IDLE.

### Workaround

Expect to receive the MCKO edge corresponding to the IDLE state upon re-enabling of MCKO after MCKO has been gated.

## ERR006967: eDMA: Possible misbehavior of a preempted channel when using continuous link mode

### Description

When using Direct Memory Access (DMA) continuous link mode Control Register Continuous Link Mode (DMA\_CR[CLM]) = 1) with a high priority channel linking to itself, if the high priority channel preempts a lower priority channel on the cycle before its last read/write sequence, the counters for the preempted channel (the lower priority channel) are corrupted. When the preempted channel is restored, it continues to transfer data past its "done" point (that is the byte transfer counter wraps past zero and it transfers more data than indicated by the byte transfer count (NBYTES)) instead of performing a single read/write sequence and retiring.

The preempting channel (the higher priority channel) will execute as expected.

### Workaround

Disable continuous link mode (DMA\_CR[CLM]=0) if a high priority channel is using minor loop channel linking to itself and preemption is enabled. The second activation of the preempting channel will experience the normal startup latency (one read/write sequence + startup) instead of the shortened latency (startup only) provided by continuous link mode.

## ERR006976: MC\_ME: SAFE mode not entered immediately on hardware-triggered SAFE mode request during STOP0 mode

### Description

If a SAFE mode request is generated by the Reset Generation Module (MC\_RGM) while the chip is in STOP0 mode, the chip does not immediately enter SAFE mode if STOP0 is configured as follows in the STOP0 Mode Configuration register (ME\_STOP0\_MC):

- the system clock is disabled (ME\_STOP0\_MC[SYSCLK] = 0b1111)
- the internal RC oscillator is enabled (ME\_STOP0\_MC[IRCON] = 0b1)

In this case, the chip will remain in STOP0 mode until an interrupt request or wakeup event occurs, causing the chip to return to its previous RUNx mode, after which the still pending SAFE mode request will cause the chip to enter SAFE mode.

### Workaround

There are two possibilities.

1. Configure the internal RC oscillator to be disabled during STOP0 mode (ME\_STOP0\_MC[IRCON] = 0b0) if the device supports it.

2. Prior to entering STOP0 mode, configure all hardware-triggered SAFE mode requests that need to cause an immediate transition from STOP0 to SAFE mode to be interrupt requests. This is done in the MC\_RGM's 'Functional' Event Alternate Request register (RGM\_FEAR).

## ERR007274: LINFlexD: Consecutive headers received by LIN Slave triggers the LIN FSM to an unexpected state

### Description

As per the Local Interconnect Network (LIN) specification, the processing of one frame should be aborted by the detection of a new header sequence and the LIN Finite State Machine (FSM) should move to the protected identifier (PID) state. In the PID state, the LIN FSM waits for the detection of an eight bit frame identifier value.

In LINFlexD, if the LIN Slave receives a new header instead of data response corresponding to a previous header received, it triggers a framing error during the new header's reception and returns to IDLE state.

### Workaround

The following three steps should be followed -

- 1) Configure slave to Set the MODE bit in the LIN Time-Out Control Status Register (LINTCSR[MODE]) to '0'.
- 2) Configure slave to Set Idle on Timeout in the LINTCSR[IOT] register to '1'. This causes the LIN Slave to go to an IDLE state before the next header arrives, which will be accepted without any framing error.
- 3) Configure master to wait for Frame maximum time (T Frame\_Maximum as per LIN specifications) before sending the next header.

Note:

$$T_{Header\_Nominal} = 34 * T_{Bit}$$
$$T_{Response\_Nominal} = 10 * (N_{Data} + 1) * T_{Bit}$$
$$T_{Header\_Maximum} = 1.4 * T_{Header\_Nominal}$$
$$T_{Response\_Maximum} = 1.4 * T_{Response\_Nominal}$$
$$T_{Frame\_Maximum} = T_{Header\_Maximum} + T_{Response\_Maximum}$$

where TBit is the nominal time required to transmit a bit and NData is number of bits sent.

## ERR007322: FlexCAN: Bus Off Interrupt bit is erroneously asserted when soft reset is performed while FlexCAN is in Bus Off state

### Description

Under normal operation, when FlexCAN enters in Bus Off state, a Bus Off Interrupt is issued to the CPU if the Bus Off Mask bit (CTRL[BOFF\_MSK]) in the Control Register is set. In consequence, the CPU services the interrupt and clears the ESR[BOFF\_INT] flag in the Error and Status Register to turn off the Bus Off Interrupt.

In continuation, if the CPU performs a soft reset after servicing the bus off interrupt request, by either requesting a global soft reset or by asserting the MCR[SOFT\_RST] bit in the Module Configuration Register, once MCR[SOFT\_RST] bit transitions from 1 to 0 to acknowledge the soft reset completion, the ESR[BOFF\_INT] flag (and therefore the Bus Off Interrupt) is re-asserted.

The defect under consideration is the erroneous value of Bus Off flag after soft reset under the scenario described in the previous paragraph.

The Fault Confinement State (ESR[FLT\_CONF] bit field in the Error and Status Register) changes from 0b11 to 0b00 by the soft reset, but gets back to 0b11 again for a short period, resuming after certain time to the expected Error Active state (0b00). However, this late correct state does not reflect the correct ESR[BOFF\_INT] flag which stays in a wrong value and in consequence may trigger a new interrupt service.

### Workaround

To prevent the occurrence of the erroneous Bus Off flag (and eventual Bus Off Interrupt) the following soft reset procedure must be used:

1. Clear CTRL[BOFF\_MSK] bit in the Control Register (optional step in case the Bus Off Interrupt is enabled).
2. Set MCR[SOFT\_RST] bit in the Module Configuration Register.
3. Poll MCR[SOFT\_RST] bit in the Module Configuration Register until this bit is cleared.
4. Wait for 4 peripheral clocks.
5. Poll ESR[FLTCONF] bit in the Error and Status Register until this field is equal to 0b00.
6. Write "1" to clear the ESR[BOFF\_INT] bit in the Error and Status Register.
7. Set CTRL[BOFF\_MSK] bit in the Control Register (optional step in case the Bus Off Interrupt is enabled).

### ERR007394: MC\_ME: Incorrect mode may be entered on low-power mode exit.

#### Description

For the case when the Mode Entry (MC\_ME) module is transitioning from a run mode (RUN0/1/2/3) to a low power mode (HALT/STOP/STANDBY\*) if a wake-up or interrupt is detected one clock cycle after the second write to the Mode Control (ME\_MCTL) register, the MC\_ME will exit to the mode previous to the run mode that initiated the low power mode transition.

Example correct operation DRUN->RUN1-> RUN3->STOP->RUN3

Example failing operation DRUN->RUN1-> RUN3->STOP->RUN1

Note STANDBY mode is not available on all MPC56xx microcontrollers

#### Workaround

To ensure the application software returns to the run mode (RUN0/1/2/3) prior to the low power mode (HALT/STOP/STANDBY\*) it is required that the RUNx mode prior to the low power mode is entered twice.

The following example code shows RUN3 mode entry prior to a low power mode transition.

```
ME.MCTL.R = 0x70005AF0; /* Enter RUN3 Mode & Key */
ME.MCTL.R = 0x7000A50F; /* Enter RUN3 Mode & Inverted Key */
while (ME.GS.B.S_MTRANS) {} /* Wait for RUN3 mode transition to complete */
ME.MCTL.R = 0x70005AF0; /* Enter RUN3 Mode & Key */
ME.MCTL.R = 0x7000A50F; /* Enter RUN3 Mode & Inverted Key */
while (ME.GS.B.S_MTRANS) {} /* Wait for RUN3 mode transition to complete */
/* Now that run mode has been entered twice can enter low power mode */
/* (HALT/STOP/STANDBY*) when desired. */
```

### ERR007589: LINFlexD: Spurious timeout error when switching from UART to LIN mode or when resetting LINTCSR[MODE] bit in LIN mode

#### Description

If the LINFlexD module is enabled in Universal Asynchronous Receiver/Transmitter (UART) mode and the value of the MODE bit of the LIN Timeout Control Status register (LINTCSR) is 0 (default value after reset), any activity on the transmit or receive pins will cause an unwanted change in the value of the 8-bit field Output Compare Value 2 (OC2) of the LIN Output Compare register (LINOOCR).



If the LINFlexD module is enabled in LIN mode and the value of the MODE bit of the LIN Timeout Control Status register (LINTCSR) is changed from '1' to '0', then the old value of the Output Compare Value 1 (OC1) and Output Compare Value 2 (OC2) of the LIN Output Compare register (LINOOCR) is retained.

As a consequence, if the module is reconfigured from UART to Local Interconnect Network (LIN) mode, or LINTCSR MODE bit is changed from '1' to '0', an incorrect timeout exception is generated when the LIN communication starts.

#### Workaround

If the LINFlexD module needs to be switched from UART mode to LIN mode, before writing UARTCR[UART] to 1, ensure that the LINTCSR[MODE] is first set to 1.

If the LINFlexD module is in LIN mode and LINTCSR[MODE] needs to be switched from 1 to 0 in between frames, the LINOOCR must be set to 0xFFFF by software.

### **ERR007688: RTC: An API interrupt may be triggered prematurely after programming the API timeout value**

#### Description

When the API is enabled (RTCC[APIEN]), the API interrupt flag is enabled (RTCC[APIIE]) and the API timeout value (RTCC[APIVAL]) is programmed the next API interrupt may be triggered before the programmed API timeout value. Successive API Interrupts will be triggered at the correct time interval.

#### Workaround

The user must not use the first API interrupt for critical timing tasks.

### **ERR007938: ADC: Possibility of missing CTU conversions**

#### Description

The CTU prioritizes and schedules trigger sources so that the ADC will receive only one CTU trigger at a time. However, whilst a Normal or Injected ADC conversion is ongoing as the ADC moves state from IDLE-to-SAMPLE, SAMPLE-to-WAIT, WAIT-to-SAMPLE and WAIT-to-IDLE there are 2 clock cycles at the state transition that a CTU trigger may be missed by the ADC.

#### Workaround

To ensure all CTU triggers are received at the ADC Normal and Injected modes must be disabled.

### **ERR007953: ME: All peripherals that will be disabled in the target mode must have their interrupt flags cleared prior to target mode entry**

#### Description

Before entering the target mode, software must ensure that all interrupt flags are cleared for those peripheral that are programmed to be disabled in the target mode. A pending interrupt from these peripherals at target mode entry will block the mode transition or possibly lead to unspecified behaviour.

#### Workaround

For those peripherals that are to be disabled in the target mode the user has 2 options:

1. Mask those peripheral interrupts and clear the peripheral interrupt flags prior to the target mode request.
2. Through the target mode request ensure that all those peripheral interrupts can be serviced by the core.



## ERR008227: CGM & ME: The peripheral set clock must be active during a peripheral clock enable or disable request

### Description

An individual peripheral clock can be enabled or disabled for a target mode via the Mode Entry Peripheral Control register (ME\_PCTL) and the Mode Entry RUN/Low Power Peripheral Configuration register (ME\_RUN\_PC & ME\_LP\_PC). For this process to complete the user must ensure that the peripheral set clock relative to the specific peripheral is enabled for the duration of the current-mode-to-target-mode transition. The peripheral set clock is configured at the Clock Generation Module System Clock Divider Configuration Register (CGM\_SC\_DC).

A caveat for FlexCAN is for the case when the FXOSC is selected for the CAN Engine Clock Source (FLEXCAN\_CTRL[CLK\_SRC]). In this instance to enable or disable the FlexCAN peripheral clock the user must ensure FXOSC is enabled through the target mode transition i.e. FXOSC must be enabled for the target mode.

### Workaround

To enable a peripheral clock:

1. Enable the peripheral set clock at CGM\_SC\_DC.
2. Enable the peripheral clock for the target mode at ME\_PCTL & ME\_RUN\_PC/ ME\_LP\_PC.
3. Note steps 1 & 2 are interchangeable.
4. Transition to the target mode to enable the peripheral clock.

To disable a peripheral clock:

1. Disable the peripheral clock for the target mode at ME\_PCTL & ME\_RUN\_PC/ ME\_LP\_PC.
2. Transition to the target mode to disable the peripheral clock.
3. Optionally disable peripheral set clock at CGM\_SC\_DC. Note to check other peripherals in this peripheral set are not required.

## ERR008933: LINFlexD: Inconsistent sync field may cause an incorrect baud rate and the Sync Field Error Flag may not be set

### Description

When the LINFlexD module is configured as follows:

1. LIN (Local Interconnect Network) slave mode is enabled by clearing the Master Mode Enable bit in the LIN Control Register 1 (LINCR1[MME] = 0b0)
2. Auto synchronization is enabled by setting LIN Auto Synchronization Enable (LINCR1[LASE] = 0b1)

The LINFlexD module may automatically synchronize to an incorrect baud rate without setting the Sync Field Error Flag in the LIN Error Status register (LINESR[SFEF]) in case Sync Field value is not equal to 0x55, as per the Local Interconnect Network (LIN) specification.

The auto synchronization is only required when the baud-rate in the slave node can not be programmed directly in software and the slave node must synchronize to the master node baud rate.

### Workaround

There are 2 possible workarounds.

Workaround 1:

When the LIN time-out counter is configured in LIN Mode by clearing the MODE bit of the LIN Time-Out Control Status register (LINTCSR[MODE]= 0x0):

1. Set the LIN state Interrupt enable bit in the LIN Interrupt Enable register (LINIER[LSIE] = 0b1)

2. When the Data Reception Completed Flag is asserted in the LIN Status Register (LINSR[DRF] = 0b1) read the LIN State field (LINSR[LINS])
3. If LINSR[LINS]= 0b0101, read the Counter Value field of the LIN Time-Out Control Status register (LINTCSR[CNT]), otherwise repeat step 2
4. If LINTCSR[CNT] is greater than 0xA, discard the frame.

When the LIN Time-out counter is configured in Output Compare Mode by setting the LINTCSR[MODE] bit:

1. Set the LIN State Interrupt Enable bit in the LIN Interrupt Enable register (LINIER[LSIE])
2. When the Data Reception Completed flag bit is asserted in the LIN Status Register (LINSR[DRF] = 0b1), read the LINSR[LINS] field
3. If LINSR[LINS]= 0b0101, store LINTCSR[CNT] value in a variable (ValueA), otherwise repeat step 2
4. Clear LINSR[DRF] flag by writing LINSR[LINS] field with 0xF
5. Wait for LINSR[DRF] to become asserted again and read LINSR[LINS] field
6. If LINSR[LINS] = 0b0101, store LINTCSR[CNT] value in a variable (ValueB), else repeat step 4
7. If ValueB - ValueA is greater than 0xA, discard the frame

Workaround 2:

Do not use the auto synchronization feature (disable with LINCR1[LASE] = 0b0) in LIN slave mode.

## **ERR008951: I2C: Attempting a start cycle while the bus is busy may generate a short clock pulse**

### **Description**

When the I2C (Inter-Integrated Circuit) is operating in a multi-master network and a start cycle is attempted by the I2C device when the bus is busy, the attempting master will lose arbitration as expected but a short extra clock cycle is generated in the bus. After losing arbitration, the master switches to slave mode but it does not detect the short clock pulse. The acknowledge signal is expected at the ninth clock by the current bus master but it is not sent as expected due to the undetected short clock pulse.

### **Workaround**

Software must ensure that the I2C BUS is idle by checking the bus busy bit in the I2C Bus Status Register (I2C\_IBSR.IBB) before switching to master mode and attempting a Start cycle.

## **ERR008970: LINFlexD: Spurious bit error in extended frame mode may cause an incorrect Idle State**

### **Description**

The LINFlexD module may set a spurious Bit Error Flag (BEF) in the LIN Error Status Register (LINESR), when the LINFlexD module is configured as follows:

- Data Size greater than eight data bytes (extended frames) by configuring the Data Field Length (DFL) bitfield in the Buffer Identifier Register (BIDR) with a value greater than seven (eight data bytes)
- Bit error is able to reset the LIN state machine by setting Idle on Bit Error (IOBE) bit in the LIN Control Register 2 (LINCR2)

As consequence, the state machine may go to the Idle State when the LINFlexD module tries the transmission of the next eight bytes, after the first ones have been successfully transmitted and Data Buffer Empty Flag (DBEF) was set in the LIN Status Register (LINSR).

## Workaround

Do not use the extended frame mode by configuring Data Field Length (DFL) bit-field with a value less than eight in the Buffer Identifier Register (BIDR) ( $BIDR[DFL] < 8$ )

## ERR009682: SPI: Inconsistent loading of shift register data into the receive FIFO following an overflow event

### Description

In the Serial Peripheral Interface (SPI) module, when both the receive FIFO and shift register are full (Receive FIFO Overflow Flag bit in Status Register is set ( $SR[RFOF] = 0b1$ )) and then the Clear Rx FIFO bit in Module Configuration Register ( $MCR[CLR_RXF]$ ) is asserted to clear the receive FIFO, shift register data is loaded into the receive FIFO after the clear operation completes.

### Workaround

1. Avoid a receive FIFO overflow condition ( $SR[RFOF]$  should never be  $0b1$ ). To do this, monitor the RX FIFO Counter field of the Status Register ( $SR[RXCTR]$ ) which indicates the number of entries in receive FIFO and clear before the counter equals the FIFO depth.
2. Alternatively, after every receive FIFO clear operation ( $MCR[CLR_RXF] = 0b1$ ) following a receive FIFO overflow ( $SR[RFOF] = 0b1$ ) scenario, perform a single read from receive FIFO and discard the read data.

## ERR009764: SARADC : DMA interface limitation depending on PBRIDGE/SARADC clock ratio

### Description

The Successive Approximation Register Analog-to-Digital Converter (SARADC) modules can trigger a Direct Memory Access (DMA) request through the DMA Enable (DMAE) register interface.

When the SARADC clock ( $SAR\_CLK$ ) frequency is slower than half of the peripheral bridge ( $PBRIDGE\_CLK$ ) clock frequency, the SARADC may trigger a spurious transfer request to the DMA module after the completion of a first valid transfer.

### Workaround

Setting the DMA clear sequence enable (DCLR) bit in the DMAE register ( $DMAE[DCLR] = 1$ ) forces the clearing of the DMA request on read access to the data register and therefore prevents the spurious DMA transfer request.

In case the Internal Channel Data Registers (ICDRn) are only accessed through DMA module (i.e. there are no bus accesses to ICDRn registers triggered by other than DMA bus master when the  $DMAE[DMAEN]$  bit is set), it is possible to configure  $DMAE[DCLR]$  bit to '1'. This will clear DMA transfer request on the first DMA read access, ensuring both that DMA triggered transfer will complete successfully and that no other spurious DMA request will be triggered.

This work-around can be applied when any of below condition can be met:

- frequency ratio  $PBRIDGE\_CLK/SAR\_CLK \leq 8/3$
- $PBRIDGE\_CLK$  is 40MHz and  $SAR\_CLK \geq 14MHz$

## ERR009976: DSPI: Incorrect data received by master with Modified transfer format enabled when using Continuous serial communication clock mode

### Description

When the Deserial Serial Peripheral Interface (DSPI) module is configured as follows:

1. Master mode is enabled (Master/Slave Mode Select bit in Module Configuration Register is set ( $DSPI\_MCR[MSTR] = 0b1$ ))
2. Modified transfer format is enabled (Modified Transfer Format Enable bit in Module Configuration Register is set ( $DSPI\_MCR[MTFE] = 0b1$ ))

3. Continuous serial communication clock mode is enabled (Continuous SCK Enable bit in Module Configuration Register is set (DSPI\_MCR [CONT\_SCKE] = 0b1))

In this configuration if the frame size of the current frame is greater than the frame size of the next received frame, corrupt frames are received in two scenarios:

- a) Continuous Peripheral Chip Select Enable bit in PUSH TX FIFO Register is set (DSPI\_PUSHR [CONT] = 0b1)
- b) DSPI\_PUSHR [CONT] = 0b0 and lower significant bit of the frame is transferred first (LSB first bit in Clock and Transfer Attributes Register is set (DSPI\_CTAR [LSBFE] = 0b1))

#### Workaround

To receive correct frames:

- a) When DSPI\_PUSHR [CONT] = 0b1, configure the frame size of the current frame less than or equal to the frame size of the next frame (for all frames).
- b) When DSPI\_PUSHR [CONT] = 0b0, configure DSPI\_CTAR [LSBFE] = 0b0. Alternatively, configure the frame size of the current frame less than or equal to the frame size of the next frame (for all frames).

Make sure that for all received frames, the bits are read equal to their respective frame sizes and any extra bits during POP operation are masked.

### ERR009978: eMIOS: Unexpected channel flag assertion during GPIO to MCB mode transition

#### Description

When changing an Enhanced Modular IO Subsystem (eMIOS) channel mode from General Purpose Input/Output (GPIO) to Modulus Counter Buffered (MCB) mode, the channel flag in the eMIOS Channel Status register (eMIOS\_Sn[FLAG]) may incorrectly be asserted. This will cause an unexpected interrupt or DMA request if enabled for that channel.

#### Workaround

In order to change the channel mode from GPIO to MCB without causing an unexpected interrupt or DMA request, perform the following steps:

- (1) Clear the FLAG enable bit in the eMIOS Control register (eMIOS\_Cn[FEN] = 0).
- (2) Change the channel mode (eMIOS\_Cn[MODE]) to the desired MCB mode.
- (3) Clear the channel FLAG bit by writing '1' to the eMIOS Channel Status register FLAG field (eMIOS\_Sn[FLAG] = 1).
- (4) Set the FLAG enable bit (eMIOS\_Cn[FEN] = 1) to re-enable the channel interrupt or DMA request reaction.

### ERR010755: DSPI: Transmit and Receive FIFO fill flags in status register is not cleared when DMA is improperly configured

#### Description

The Deserial/Serial Peripheral Interface Transmit and Receive First In/First Out (FIFO) buffers can request additional information to be transferred via the Direct Memory Access (DMA) module when either the Transmit or Receive FIFO Fill/Drain Flags are set in the DSPI Status Register (SR[TFFF/RDFD]). However, the Transmit Fill Flag indicates that at least 1 location each (2 bytes each) in the Transmit and Command FIFOs is available to be written. It does not indicate that the FIFO is empty. Similarly, Receive FIFO fill flag only indicates at least 1 location (2 bytes) of the FIFO is available to be read. It does not indicate that the FIFO is full. If the DMA is configured to transfer more than 1 FIFO location size of data, the FIFO Fill/Drain Flags may not be properly cleared indicating that the FIFO is not full even when the FIFO is actually full (for Transmit FIFO) and not empty when the FIFO is actually empty (for Receive FIFO).

### Workaround

Properly configure the DMA to fill/drain only 2 bytes to Transmit, Command and Receive FIFOs. Use the DMA loop to transfer more data if needed.

## **ERR011235: EMIOS: Any Unified Channel running in OPWMB or OPWMCB mode may function improperly if the source counter bus is generated by Unified channel in MC mode**

### Description

The Unified channel (UC) configured in Center Aligned Output Pulse Width Modulation Buffered (OPWMCB) or Output Pulse Width Modulation Buffered (OPWMB) modes is not working properly when it is sourced from the UC configured in Modulus Counter (MC) mode by setting the channel control register MODE bitfield to 0x10 or 0x11 and any of its pre-scalers (internal or global) divider ratio is higher than 1.

### Workaround

When a counter bus is generated by the UC set in the MC mode with any pre-scaler (internal or global) divider ratio higher than 1, don't use this counter bus for the UC set in OPWMCB or OPWMB mode.

## **ERR011293: EMIOS: For any UC operating in OPWFMB mode the Channel Count register should not be written with a value greater than Channel B Data register value**

### Description

For any Unified Channel (UC) running in Output Pulse-Width and Frequency Modulation Buffered (OPWFMB) mode, Channel Control Register MODE bitfield = 7'h1011000 or 7'h1011010, the internal counter runs from 0x1 to Channel B Data register value. The internal counter can be overwritten by software using the Channel Count register during 'freeze' operation.

If a counter wrap occurs due to overwriting of the counter with a value greater than its expiry value (B Data Register value); then the output signal behavior cannot be guaranteed.

### Workaround

For any UC operating in OPWFMB mode the Channel Count register should not be written with a value greater than Channel B Data register value.

## **ERR011294: EMIOS: OPWFMB and MCB mode counter rollover resets the counter to 0x0 instead of 0x1 as mentioned in the specification**

### Description

When the enhanced Modular Input/Output System (eMIOS) is used in Output Pulse-Width and Frequency Modulation Buffered (OPWFMB) or Modulus Counter Buffered (MCB) modes, when the counter rolls over, the counter returns to 0x0 instead of 0x1 as specified in the reference manual.

### Workaround

In order to avoid the counter wrap condition:

1. Make sure internal counter value is within the 0x1 to (B1 register) value range when the OPWFMB mode is entered.
2. Overwrite of Channel Count register by forcing 'freeze' in OPWFMB mode should not be outside the range of 0x1 to (B register) value.

## ERR011295: EMIOS: In OPWFMB mode, A1/B1 registers do not get reloaded with A2/B2 register values if counter value returns 0x1 after counter wrap condition

### Description

In Output Pulse-Width and Frequency Modulation Buffered (OPWFMB) mode, A1/B1 registers do not get reloaded with A2/B2 register values if counter value returns 0x1 after counter wrap condition.

In order to avoid the counter wrap condition make sure internal counter value is within the 0x1 to B1 register value range when the OPWFMB mode is entered. Also overwriting of Channel Count register by forcing 'freeze' in OPWFMB mode should not take internal counter outside 0x1 to B register value.

### Workaround

In order to avoid the counter wrap condition:

1. Make sure internal counter value is within the 0x1 to (B1 register) value range when the OPWFMB mode is entered.
2. Overwrite of Channel Count register by forcing 'freeze' in OPWFMB mode should not be outside the range of 0x1 to (B register) value.

## ERR050459: SXOSC: Clock output may contain extra clock pulses in Normal mode

### Description

The 32 kHz Slow External Crystal Oscillator (SXOSC) may generate an extra clock pulse per clock period when configured in Normal mode using an external crystal. The SXOSC correctly generates positive clock edges aligned to the external crystal clock transitions but an extra clock pulse may be generated near the positive edge of the clock waveform. The SXOSC interface to the external crystal is not affected. This issue may only occur in the default Normal mode and operates as expected in Bypass mode (i.e. OSC\_CTL[OSCBYP]=1).

The SXOSC clock source may be selected as the clock source for the Real Time Counter and Autonomous Periodic Interrupt (RTC/API) and also as the clock to be measured in the CMU Frequency Meter (via the CMU\_FDR register). The RTC/API and CMU Frequency Meter counters may get an extra clock per SXOSC clock period causing a higher than expected count (affecting the calculated time or wakeup duration) or may theoretically cause a corrupted count value. The occurrence of the potential clock pulse may vary from clock period to clock period ranging from no extra clock pulse to one extra clock pulse per period. SXOSC may also be selected to be reflected to the CLKOUT pin. Worse case conditions to produce an extra clock pulse are lower temperatures.

### Workaround

Use the SXOSC in Bypass mode instead of Normal mode by setting OSC\_CTL[OSCBYP]. Bypass mode does not support an external crystal and thus an external clock source is needed.

Select other clock sources for the RTC/API and CMU Frequency Meter. The RTC/API supports other clock sources which include the 128 kHz Slow Internal RC Oscillator (SIRC), 16 MHz Fast Internal RC Oscillator (FIRC), and 4-16 MHz Fast External Crystal Oscillator (FXOSC).

## ERR050575: eMIOS: Any Unified Channel running in OPWMCB mode may function improperly if the lead or trail dead time insertion features is used and its timebase is generated by Unified channel in MCB mode

### Description

The Unified channel (UC) configured in Center Aligned Output Pulse Width Modulation Buffered (OPWMCB) mode is not working properly when:

1. It's timebase is sourced from the UC configured in Modulus Counter Buffered (MCB) mode.

2. The lead or trail dead time insertion features is used.
3. Its channel prescaler is different than timebase channel prescaler.

**Workaround**

Channel configured in OPWMCB mode with lead or trail dead time insertion features enabled must have channel prescaler equal to the timebase channel prescaler configured in MCB mode.



# Legal information

## Definitions

**Draft** — A draft status on a document indicates that the content is still under internal review and subject to formal approval, which may result in modifications or additions. NXP Semiconductors does not give any representations or warranties as to the accuracy or completeness of information included in a draft version of a document and shall have no liability for the consequences of use of such information.

## Disclaimers

**Limited warranty and liability** — Information in this document is believed to be accurate and reliable. However, NXP Semiconductors does not give any representations or warranties, expressed or implied, as to the accuracy or completeness of such information and shall have no liability for the consequences of use of such information. NXP Semiconductors takes no responsibility for the content in this document if provided by an information source outside of NXP Semiconductors.

In no event shall NXP Semiconductors be liable for any indirect, incidental, punitive, special or consequential damages (including - without limitation - lost profits, lost savings, business interruption, costs related to the removal or replacement of any products or rework charges) whether or not such damages are based on tort (including negligence), warranty, breach of contract or any other legal theory.

Notwithstanding any damages that customer might incur for any reason whatsoever, NXP Semiconductors' aggregate and cumulative liability towards customer for the products described herein shall be limited in accordance with the Terms and conditions of commercial sale of NXP Semiconductors.

**Right to make changes** — NXP Semiconductors reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice. This document supersedes and replaces all information supplied prior to the publication hereof.

**Suitability for use** — NXP Semiconductors products are not designed, authorized or warranted to be suitable for use in life support, life-critical or safety-critical systems or equipment, nor in applications where failure or malfunction of an NXP Semiconductors product can reasonably be expected to result in personal injury, death or severe property or environmental damage. NXP Semiconductors and its suppliers accept no liability for inclusion and/or use of NXP Semiconductors products in such equipment or applications and therefore such inclusion and/or use is at the customer's own risk.

**Applications** — Applications that are described herein for any of these products are for illustrative purposes only. NXP Semiconductors makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

Customers are responsible for the design and operation of their applications and products using NXP Semiconductors products, and NXP Semiconductors accepts no liability for any assistance with applications or customer product design. It is customer's sole responsibility to determine whether the NXP Semiconductors product is suitable and fit for the customer's applications and products planned, as well as for the planned application and use of customer's third party customer(s). Customers should provide appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP Semiconductors does not accept any liability related to any default, damage, costs or problem which is based on any weakness or default in the customer's applications or products, or the application or use by customer's third party customer(s). Customer is responsible for doing all necessary testing for the customer's applications and products using NXP Semiconductors products in order to avoid a default of the applications and the products or of the application or use by customer's third party customer(s). NXP does not accept any liability in this respect.

**Terms and conditions of commercial sale** — NXP Semiconductors products are sold subject to the general terms and conditions of commercial sale, as published at <http://www.nxp.com/profile/terms>, unless otherwise agreed in a valid written individual agreement. In case an individual agreement is concluded only the terms and conditions of the respective agreement shall apply. NXP Semiconductors hereby expressly objects to applying the customer's general terms and conditions with regard to the purchase of NXP Semiconductors products by customer.

**Suitability for use in automotive applications** — This NXP product has been qualified for use in automotive applications. If this product is used by customer in the development of, or for incorporation into, products or services (a) used in safety critical applications or (b) in which failure could lead to death, personal injury, or severe physical or environmental damage (such products and services hereinafter referred to as "Critical Applications"), then customer makes the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, safety, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP. As such, customer assumes all risk related to use of any products in Critical Applications and NXP and its suppliers shall not be liable for any such use by customer. Accordingly, customer will indemnify and hold NXP harmless from any claims, liabilities, damages and associated costs and expenses (including attorneys' fees) that NXP may incur related to customer's incorporation of any product in a Critical Application.

**Export control** — This document as well as the item(s) described herein may be subject to export control regulations. Export might require a prior authorization from competent authorities.



**Translations** — A non-English (translated) version of a document, including the legal information in that document, is for reference only. The English version shall prevail in case of any discrepancy between the translated and English versions.

**Security** — Customer understands that all NXP products may be subject to unidentified vulnerabilities or may support established security standards or specifications with known limitations. Customer is responsible for the design and operation of its applications and products throughout their lifecycles to reduce the effect of these vulnerabilities on customer's applications and products. Customer's responsibility also extends to other open and/or proprietary technologies supported by NXP products for use in customer's applications. NXP accepts no liability for any vulnerability. Customer should regularly check security updates from NXP and follow up appropriately.

Customer shall select products with security features that best meet rules, regulations, and standards of the intended application and make the ultimate design decisions regarding its products and is solely responsible for compliance with all legal, regulatory, and security related requirements concerning its products, regardless of any information or support that may be provided by NXP.

NXP has a Product Security Incident Response Team (PSIRT) (reachable at [PSIRT@nxp.com](mailto:PSIRT@nxp.com)) that manages the investigation, reporting, and solution release to security vulnerabilities of NXP products.

## Trademarks

Notice: All referenced brands, product names, service names, and trademarks are the property of their respective owners.

**NXP** — wordmark and logo are trademarks of NXP B.V.

---

Please be aware that important notices concerning this document and the product(s) described herein, have been included in section 'Legal information'.

---

© NXP B.V. 2023.

All rights reserved.

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

Date of release: 1/2023

Document identifier: MPC5607B\_1M03Y